/)
6)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
		((piezoelectric or PZT)) and flatness and porosity and (perovskite or beryllia or zirconia	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/06 08:48
L1	308	310/363.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR.	OFF	2006/03/06 08:48
L2	273	310/364.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/06 08:48
S1	0	"10722157"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:26
S2	1	"10/722157"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 15:56
S3	2	"11034321"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 15:56
S4	203764	(piezoelectric or PZT)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:42
S5	31452	(piezoelectric or PZT) and actuator	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:42

				···		
S6	1841	(piezoelectric or PZT) and actuator and (roughness or flatness)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:43
S7	793	(piezoelectric or PZT) and actuator and (flatness)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:43
S8	1	(piezoelectric or PZT) and actuator and (flatness) and uneveness	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:45
S9	223	(piezoelectric or PZT) and actuator and (flatness) and dielectric	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:45
S10	117	(piezoelectric or PZT) and actuator and (flatness) and dielectric and ceramic	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:47
S11	21	((piezoelectric or PZT) adj actuator) and (flatness) and dielectric and ceramic	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 19:13
S12	1	((piezoelectric or PZT) adj actuator) and (flatness) and dielectric and ceramic and porosity	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 18:52
S13	216	((piezoelectric or PZT) adj actuator) and (flatness)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 19:13

S14	24	((piezoelectric or PZT) adj actuator) same (flatness)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 19:25
S15	242	((piezoelectric or PZT) adj actuator) and zirconia	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/23 19:25
S16	135	((piezoelectric or PZT) adj actuator) and zirconia and crystal	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:34
S17	15	((piezoelectric or PZT) adj actuator) and zirconia and crystal and flatness	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 13:21
S18	105	264/671.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 13:13
S19	36	((piezoelectric or PZT) adj actuator) and "264"/\$8.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 13:30
S20	2	((piezoelectric or PZT) adj actuator) and "264"/\$8.ccls. and flatness	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 13:37
S21	30	((piezoelectric or PZT)) and "264"/\$8.ccls. and flatness	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 13:37

3/6/06 8:49:05 AM C:\Documents and Settings\clopez\My Documents\EAST\Workspaces\10722157.wsp

			· · · · · · · · · · · · · · · · · · ·			
S22	6	("4019915" "4078938" "4255272" "4766671" "5085720").PN. OR ("5527501"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/24 15:50
S23	57	("3948706" "4137628" "4345955" "4490429" "4510000" "4620264" "4641425" "4654095" "4680859").PN. OR ("4766671").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/24 16:34
S24	12	("3948706" "4137628" "4345955" "4490429" "4510000" "4620264" "4641425" "4654095" "4680859").PN. OR ("4766671").URPN. and flatness	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/24 16:31
S25	10	("3948706" "4137628" "4345955" "4490429" "4510000" "4620264" "4641425" "4654095" "4680859").PN. OR ("4766671").URPN. and flatness and porosity	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/24 16:31
S26	7	((piezoelectric or PZT) adj actuator) and flatness and porosity .	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:37
S27	101	((piezoelectric or PZT)) and flatness and porosity	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:48
S28	6	((piezoelectric or PZT)) and flatness.clm. and porosity	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:38
S29	2	((piezoelectric or PZT)) and flatness.clm. and porosity.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:38
S30	35	((piezoelectric or PZT)) and flatness and porosity and (perovskite or beryllia or zirconia)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/24 16:50

S31	61	((piezoelectric or PZT)) and flatness and porosity and (perovskite or beryllia or zirconia or bismuth or tungsten or alumina or mullite)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/25 15:53
S32	305	264/614.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ,	OFF	2006/02/25 15:53
S33	105	264/671.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/25 15:53